

Location Information				Owner-Owned Portion										Customer-Owned Portion										Other Potential Sources of Lead				Additional Information to Assign Task Monitoring Tiering				Lead Service Line Replacement (LSLR)			
Street Address*	City*	Sensitive Population†	Disadvantaged Neighborhood‡	System-Owned Portion Service Line Material Classification*	† Non-Lead in Column F, Was Material Ever Previously Lead?*	Service Line Installation Date (System Side)	Service Line Size (inches) (System Side)	Basic of Material Classification (System Side)*	Was Service Line Material Field Verified? (System Side)*	Describe the Field Verification Method (System Side)	Date of Field Verification (System Side)	Notes (System Side)	Customer-Owned Portion Service Line Material Classification*	Service Line Installation Date (Customer Side)	Service Line Size (inches) (Customer Side)	Basic of Material Classification (Customer Side)*	Was Service Line Material Field Verified? (Customer Side)*	Describe the Field Verification Method (Customer Side)	Date of Field Verification (Customer Side)	Notes (Customer Side)	Is there a Lead Connection?	Is there Lead Solder in the Service Line?*	Lead Other Frangibles and Equipment Connected to the Service Line at Customer's Location	Building Type Connected to Service Line*	Point-of-Entry or Point-of-Exit at Meter Present?	Does the Interior Building Plumbing Contain Copper pipes with Lead Solder Installed Before Your State's Lead Ban (Year)?	Current LCR Sample Size	Date of System Owned LSLR	Date of Customer-Owned LSLR						
440 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	02/2024	Built 1974	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
441 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	02/2024	Built 1974	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
439 West Spencer Road	Hurt	No	Yes	Non-Lead- Copper	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Plastic	3/4		Field inspection	Yes	Customer self-identification	02/2024	Built 1983	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
435 West Spencer Road	Hurt	No	Yes	Non-Lead- Copper	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Plastic	1/2		Field inspection	Yes	Customer self-identification	03/2024	Built 1963	No	No		Single Family Residence	Unknown	No	Yes	No							
439 West Spencer Road	Hurt	No	Yes	Non-Lead- Copper	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Plastic	3/4		Field inspection	Yes	Customer self-identification	02/2024	Built 1963	No	No		Single Family Residence	Unknown	No	Yes	No							
435 West Spencer Road	Hurt	No	Yes	Non-Lead- Copper	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Plastic	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1968	No	No		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	02/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	02/2024	Built 1970	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
439 West Spencer Road	Hurt	No	Yes	Non-Lead- Copper	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1966	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
437 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Plastic	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1963	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
435 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Plastic	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1967	No	No		Single Family Residence	Unknown	No	Yes	No							
434 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Plastic	1-1/2		Field inspection	Yes	Customer self-identification	02/2024	Built 1964	No	No		Single Family Residence	Unknown	No	Yes	No							
434 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Plastic	3/4		Field inspection	Yes	Customer self-identification	02/2024	Built 1965	No	No		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Plastic	3/4		Field inspection	Yes	Customer self-identification	02/2024	Built 1965	No	No		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Plastic	3/4		Field inspection	Yes	Customer self-identification	02/2024	Built 1965	No	No		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Plastic	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	No		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	02/2024	Built 1966	No	No		Single Family Residence	Unknown	No	Yes	No							
437 West Spencer Road	Hurt	No	Yes	Non-Lead- Copper	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1966	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
435 West Spencer Road	Hurt	No	Yes	Non-Lead- Copper	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1966	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
435 West Spencer Road	Hurt	No	Yes	Non-Lead- Copper	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1966	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
438 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know		Single Family Residence	Unknown	No	Yes	No							
430 West Spencer Road	Hurt	No	Yes	Non-Lead- Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead- Copper	3/4		Field inspection	Yes	Customer self-identification	06/2024	Built 1961	No	Don't Know													

Location Information

Street Address*

City*

Sensitive Population*

Disadvantaged Neighborhood*

System-Owned Portion

Service Line Material Classification*

Item Owned in Column F, Was Material Ever Previously Replaced?

Service Line Installation Date (System Side)

Service Line Size (Inches) (System Side)

Basic Material Classification (System Side)*

Was Service Line Material Field Verified? (System Side)*

Describe the Field Verification Method (System Side)

Date of Field Verification (System Side)

Notes (System Side)

Customer-Owned Portion

Service Line Material Classification*

Item Owned in Column F, Was Material Ever Previously Replaced?

Service Line Installation Date (Customer Side)

Service Line Size (Inches) (Customer Side)

Basic Material Classification (Customer Side)*

Was Service Line Material Field Verified? (Customer Side)*

Describe the Field Verification Method (Customer Side)

Date of Field Verification (Customer Side)

Notes (Customer Side)

Is there a Lead Connector?

Is there Lead Service Line in the Service Line?

Lost Other Findings and Equipment Connected to the Hole/Connection Contained

Building Type Connected to Service Line*

Point of Entry or Point of Exit Treatment Present?

Does the Interior Building Plumbing Contains Copper Joints with Lead-Solder Installed Before Your State's Lead Ban (e.g., 1986)?

Current CORC Sampling Site?

Date of System Owned LSLR

Date of Customer Owned LSLR

212 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Copper	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1950	No	Don't Know	No	Single Family Residence	Unknown	Unknown	No	Unknown	No		
214 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
216 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
218 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
220 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
222 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
224 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
226 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
228 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
230 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
232 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
234 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
236 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
238 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
240 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
242 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
244 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
246 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
248 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
250 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
252 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
254 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
256 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
258 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
260 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
262 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
264 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
266 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
268 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
270 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
272 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
274 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
276 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
278 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
280 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
282 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
284 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
286 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
288 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
290 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
292 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
294 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
296 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
298 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
300 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
302 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
304 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
306 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
308 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
310 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic	3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	181 Buitt 1940	No	Don't Know	No	Multiple Family Residence	Unknown	Unknown	No	Unknown	No		
312 School Road	Hurt	No	Yes	Non-Lead-Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Contractor Visual Inspection	Non-Lead-Plastic																	

Location Information

City*

Sensitive Population?

Disadvantaged Neighborhood?

System-Owned Portion Service Line Material Classification**

If Non-Lead in Column F, Was Material Ever Previously Lead?

Service Line Installation Date (System Side)

Service Line Size (Inches) (System Side)

Basic of Material Classification (System Side)**

Was Service Line Material Field Verified? (System Side)*

Describe the Field Verification Method (System Side)

Date of Field Verification (System Side)

Notes (System Side)

Customer-Owned Portion Service Line Material Classification**

Service Line Installation Date (Customer Side)

Service Line Size (Inches) (Customer Side)

Basic of Material Classification (Customer Side)**

Was Service Line Material Field Verified? (Customer Side)*

Describe the Field Verification Method (Customer Side)

Date of Field Verification (Customer Side)

Notes (Customer Side)

Is there a Lead Connection?

Is there Lead Service Line in the Service Line?

Lost Other Findings or Equipment Connected to the Portion Not Connected to Building

Building Type Connected to Service Line*

Point of Entry or Point of Use Treatment Present?

Does the Interior Building Plumbing Contains Copper Pipes with Lead Solder Installed Before Your Lead Last Ran

Current Corrosion Sampling Site?

Date of System Owned LSLR

Date of Customer Owned LSLR

427 Oakwood Drive	Hurt	No	Yes	Non-Lead - Copper	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	963 Burt 1958	No	No		Single Family Residence	Unknown	Unknown	No		
428 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	364 Burt 1958	No	No		Single Family Residence	Unknown	Unknown	No		
431 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	365 Burt 1961	No	No		Single Family Residence	Unknown	Unknown	No		
433 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	366 Burt 1961, County	No	No		Single Family Residence	Unknown	Unknown	No		
434 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	367 Burt 1971	No	Don't Know		Single Family Residence	Unknown	Unknown	No		
435 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Copper	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	368 Burt 1964	No	Don't Know		Single Family Residence	Unknown	Unknown	No		
436 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	369 Burt 1967	No	No		Single Family Residence	Unknown	Unknown	No		
437 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	370 Burt 1962	No	No		Single Family Residence	Unknown	Unknown	No		
438 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	371 Burt 1962	No	No		Single Family Residence	Unknown	Unknown	No		
439 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	372 Burt 1950	No	No		Single Family Residence	Unknown	Unknown	No		
440 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	373 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
441 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	374 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
442 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	375 Burt 1955	No	No		Single Family Residence	Unknown	Unknown	No		
443 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	376 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
444 Oakwood Drive	Hurt	No	Yes	Non-Lead - Copper	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Copper	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	377 Burt 1956	No	Don't Know		Single Family Residence	Unknown	Unknown	No		
445 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	378 Burt 1965	No	No		Single Family Residence	Unknown	Unknown	No		
446 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	379 Burt 1962	No	No		Single Family Residence	Unknown	Unknown	No		
447 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	380 Burt 1959	No	No		Single Family Residence	Unknown	Unknown	No		
448 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	381 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
449 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	382 Burt 1958	No	No		Single Family Residence	Unknown	Unknown	No		
450 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	383 Burt 1961	No	No		Single Family Residence	Unknown	Unknown	No		
451 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	384 Burt 1956	No	No		Single Family Residence	Unknown	Unknown	No		
452 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	385 Burt 1964	No	No		Single Family Residence	Unknown	Unknown	No		
453 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	386 Burt 1950	No	No		Single Family Residence	Unknown	Unknown	No		
454 Oakwood Drive	Hurt	No	Yes	Non-Lead - Copper	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Copper	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	387 Burt 1955	No	No		Single Family Residence	Unknown	Unknown	No		
455 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	388 Burt 1961	No	Don't Know		Single Family Residence	Unknown	Unknown	No		
456 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	389 Burt 1963	No	No		Single Family Residence	Unknown	Unknown	No		
457 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Copper	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	390 Burt 1962	No	Don't Know		Single Family Residence	Unknown	Unknown	No		
458 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	391 Burt 1961	No	No		Single Family Residence	Unknown	Unknown	No		
459 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	392 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
460 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	393 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
461 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	394 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
462 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	395 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
463 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	396 Burt 1961	No	No		Single Family Residence	Unknown	Unknown	No		
464 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	397 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
465 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	398 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
466 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	399 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
467 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	400 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
468 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	401 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
469 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	402 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
470 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	403 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
471 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	404 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
472 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	405 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
473 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	406 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
474 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	407 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
475 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	408 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
476 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	409 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
477 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	410 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
478 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	411 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
479 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	412 Burt 1960	No	No		Single Family Residence	Unknown	Unknown	No		
480 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	413 Burt 1950	No	No		Single Family Residence	Unknown	Unknown	No		
481 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	414 Burt 1958	No	No		Single Family Residence	Unknown	Unknown	No		
482 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	415 Burt 1950	No	No		Single Family Residence	Unknown	Unknown	No		
483 Oakwood Drive	Hurt	No	Yes	Non-Lead - Plastic	No	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2024	Connector Visual Inspection	Non-Lead - Plastic	3/4		Field inspection	Yes	Visual inspection at the meter pit	06/2										

Location Information						Owner-Owned Portion						Customer-Owned Portion						Other Potential Sources				Additional Information to Assign Tag Monitoring Tiering				Lead Service Line Replacement (LSLR)			
Street Address*	City*	Sensitive Population?	Disadvantaged Neighborhood?	System Owner/Parent Service Line Material Classification*	If Non-Lead in Column F, Was Material Ever Previously Lead?	Service Line Installation Date (System Side)	Service Line Size (inches) (System Side)	Basic Material Classification (System Side)*	Was Service Line Material Field Verified? (System Side)?	Describe the Field Verification Method (System Side)	Date of Field Verification (System Side)	Notes (System Side)	Service Line Installation Date (Customer Side)	Service Line Size (inches) (Customer Side)	Basic Material Classification (Customer Side)*	Was Service Line Material Field Verified? (Customer Side)?	Describe the Field Verification Method (Customer Side)	Date of Field Verification (Customer Side)	Notes (Customer Side)	Is there a Connection?	Is there Lead Sold in the Service Line?	List Other Findings and Equipment Connected to the Service Line Contain Lead	Building Type Connected to Service Line	Point-of Entry or Point-of Use Treatment Present?	Does the Interior Building Plumbing Contain Copper pipes with Lead Solder Installed Before Your State's Lead Ban	Current LSL Sampling Site?	Date of System Owned LSLR	Date of Customer Owned LSLR	
800 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
799 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
798 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
797 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built Unknown	No	No		Single Family Residence	Unknown	No	No	No		
796 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built Unknown	No	No		Single Family Residence	Unknown	No	No	No		
795 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
794 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
793 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
792 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
791 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
790 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
789 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
788 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
787 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
786 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
785 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
784 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
783 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
782 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
781 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
780 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
779 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
778 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
777 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
776 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
775 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
774 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
773 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
772 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
771 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
770 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
769 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
768 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
767 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
766 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
765 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
764 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
763 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
762 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
761 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
760 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
759 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
758 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
757 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
756 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
755 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
754 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
753 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
752 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
751 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
750 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
749 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
748 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
747 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
746 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection	Yes	Visual self-identification	02/2024	540 Built 1994	No	No		Single Family Residence	Unknown	No	No	No		
745 Prospect Road	Hurt	No	Yes	Non-Lead - Plastic	No		3/4	Field inspection	Yes	Visual inspection at the meter pit	06/2024	Customer Visual Inspection	Non-Lead - Plastic	3/4	Field inspection														